


connector at PP0 on cable coming from Service Tube (male) rear view

← Cable



A1	VAX+	1	VAX- sense	7	V_BIAS_X1_RTN	13	V_BIAS_X24
A2	VAX-	2	V_BIAS_X21	8	V_BIAS_X11	14	V_BIAS_X12
A3	VDX-	3	V_BIAS_X2_RTN	9	VDX- sense	15	V_BIAS_X13
A4	VDX+	4	inner drain	10	VAX+ sense	16	V_BIAS_X14
		5	1/2 outer drain	11	V_BIAS_X22	17	VDX+ sense
		6	1/2 outer drain	12	V_BIAS_X23		